CLRB 2021 Utilities

*** FOR INFORMATION ONLY. No accuracy is expressed or implied. Contractor shall follow established standards of care for utility coordination.***

Bridge Number	Route	Crossing	Asset Number	QLD SUE?	Electric Water	Sewer	Telecom	Gas
1	CHESTER S- 58	LITTLE ROCKY CREEK	4959	No	Fairfield Elec. Coop: OHE approx 25' None found or observed. from EOP.	None found or observed.	Chester Telephone (TruVista): 2" conduit attached to bridge.	None found or observed.
2	CHESTER S- 300	LITTLE ROCKY BRANCH	2490	No	Fairfield Elec: New poles and line cross S-300 aprox 200' before Br.2490 approach, poles are approx	None found or observed.	TruVista: 1" conduit attached to bridges 2310 and 2490.	Chester Co Nat Gas: in vicinity, no facilities observed at bridges.
3	CHESTER S- 300	LITTLE ROCKY BRANCH	2310		20' from edge of pavement. OHE approx 19' from EOP at Br. 2310.			
4	FAIRFIELD S- 214	LITTLE CREEK	2522		Fairfield Elec. Coop: OHE over None found or observed. bridge deck.	None found or observed.	TruVista: in vicinity, not observed at bridge.	None found or observed.
5	CHEROKEE S- 97	GOFORTH CREEK	2920		Duke Energy: in vicinity, no facilities at bridge. Toad per QLD, recent markings on paveme indicate 14+ feet from EOP.		AT&T: telephone/cable attached to bridge.	None found or observed.
6	CHEROKEE S- 265	MANNING CREEK	2689		Duke Energy: In vicinity, no facilities None found or observed. at bridge.	None found or observed.	None found or observed.	Patriot's Energy: gas main crossing S-265 approx 200' south of bridge.
7	CHEROKEE S- 119	BEAR CREEK	2308	Yes	Broad River Elec. Coop: OHE close near south side of bridge. Does not cross bridge deck. Service line crossing S-119 ~50' east of bridge.	None found or observed.	AT&T: in vicinity, not attached to bridge.	None found or observed.
8	UNION S- 87	PADGETTS CREEK	2096		Broad River Electric Coop: OHE crossing S-87 at skew, close to bridge.	None found or observed.	AT&T: 2" conduit with cable under creek on east side. Not attached to bridge. Box and pedestal observed approx 4' from guardrail at south/east end of bridge.	None found or observed.

Information above was collected from Bridge Inspection Reports (BIR), surveys, site visits, and QLD SUE at select sites.