

SOUTH CAROLINA DEPARTMENT OF TRANSPORTATION  
HIGHWAY MAINTENANCE MANAGEMENT SYSTEM

**Bridge Deficiency Report**

										Work Inspection	
District	Work County	Type	Route	Aux	Off Sys	Asset ID	Priority	Activity	Status	From Date	To Date
3	OCONEE	US	76	00		4624					
Structure		Type	Route	Aux	Milepoint	Direction	Off System Description				
Insp.Date	Activity	Priority	Comp.Date	Org.Unit		Work	Insp.Date	Cleared	Name Of Inspector		
Deficiency Comment											

District: 3 - THREE

Work County: OCONEE

4624 - 20007600300-CHAUGA RIVER	US	76	00	14.84	E					
05/22/2018	801	C	04/01/2019	OCONEE- CONTRACTS/PERMITS		05/26/2020	Y	AVANT, BRANDON D.		
REPAIR SPALLED AREAS IN DECK SURFACE										
4624 - 20007600300-CHAUGA RIVER	US	76	00	14.84	E					
09/30/2024	409	A								
REMOVE DRIFT COLLECTING ON THE UPSTREAM SIDE OF BRIDGE.										
4624 - 20007600300-CHAUGA RIVER	US	76	00	14.84	E					
05/12/2022	801	C							N	
REPAIR DECK SPALLS IN CONCRETE DECK IN SPANS 2, 3, AND 5										
4624 - 20007600300-CHAUGA RIVER	US	76	00	14.84	E					
05/12/2022	805	C							N	
REPAIR BENT 2 EXPANSION JOINT FILLED WITH ASPHALT PATCHING RESTRICTING MOVEMENT. (2 LF)										
4624 - 20007600300-CHAUGA RIVER	US	76	00	14.84	E					
05/12/2022	806	C							N	
CLEAN AND PAINT BEARINGS. (52 EA)										

SOUTH CAROLINA DEPARTMENT OF TRANSPORTATION  
HIGHWAY MAINTENANCE MANAGEMENT SYSTEM

Bridge Deficiency Report

District	Work County	Type	Route	Aux	Off Sys	Asset ID	Priority	Activity	Status	Work Inspection	
										From Date	To Date
3	OCONEE	US	76	00		4624					
Structure			Type	Route	Aux	Milepoint	Direction	Off System Description			
Insp.Date	Activity	Priority	Comp.Date	Org.Unit			Work	Insp.Date	Cleared	Name Of Inspector	
Deficiency	Comment										

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 05/12/2022 809 C N  
 REPAIR BENT 4, COLUMN 2: HEAVY ABRASION AT BOTTOM FOR 80% PERIMETER X UP TO 3" DEEP. (3 SF)  
 REPAIR BENT 3, COLUMN 2 :SPALL ON SOUTH FACE AT BOTTOM FOR 1' WIDE X 4" HIGH X 3/4" DEEP WITH (1) SECONDARY EXPOSED REBAR. (1 SF)

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 05/16/2012 801 C 06/04/2012 OCONEE - BRIDGE CREW 05/14/2014 Y AIKENS WILLIAM RUSSELL  
 REPAIR SPALLING IN DECK OF SPANS 1 AND 4

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 05/16/2012 805 B 05/22/2018 D3 -BRIDGE INSPECTION 05/22/2018 Y WADE, VINCENT  
 REPAIR ALL EXPANSION JOINTS

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 09/30/2024 202 A  
 REPAIR EROSION AT THE EAST END BENT.

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 05/19/2016 801 C 10/11/2016 OCONEE - BRIDGE CREW 05/26/2020 Y AVANT, BRANDON D.  
 REPAIR SPALLED AREAS ON DECK

US-76-03

SOUTH CAROLINA DEPARTMENT OF TRANSPORTATION  
HIGHWAY MAINTENANCE MANAGEMENT SYSTEM

**Bridge Deficiency Report**

District	Work County	Type	Route	Aux	Off Sys	Asset ID	Priority	Activity	Status	Work Inspection	
										From Date	To Date
3	OCONEE	US	76	00		4624					
Structure			Type	Route	Aux	Milepoint	Direction	Off System Description			
Insp.Date	Activity	Priority	Comp.Date	Org.Unit		Work	Insp.Date	Cleared	Name Of Inspector		
Deficiency Comment											

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 07/08/2004 807 C 07/27/2009 OCONEE - BRIDGE CREW 05/14/2014 Y AIKENS WILLIAM RUSSELL  
 CLEAN AND PAINT STEEL BEARINGS

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 05/12/2022 408 C N  
 REMOVE DRIFT LOGS FROM WATERWAY UPSTREAM SIDE BENT 3 COLUMN 2 AND BENT 4

4624 - 20007600300-CHAUGA RIVER US 76 00 14.84 E  
 05/12/2022 803 C N  
 REPAIR BENT 3, SPAN 2, BEAM 3: (2) SPALLS BEGINNING AT BEARING INSERT PLATE, EACH UP TO 19" LONG X 6" HIGH X 4" UNDER X 1.5" DEEP WITH 10% SECTION LOSS TO (2) TOTAL PRESTRESSING STRANDS. (3 SF)