






## I-77 Scout Project – MM 27-25 SB Outside Lane

Core #	Core 1	Core 2
<b>Notes</b>	Good condition	Good condition
<b>Core Pictures</b>		

Core #	Core 3	Core 4
Notes	Good condition	Good condition
Core Pictures		

Core #	Core 5	Core 6
Notes	Good condition	Debonding but relatively in fair condition
Core Pictures		

## Core Log

Core #	OFGC	Asphalt Depth	PCC	Total Depth
1	1.5	5.0	15.0	21.50
2	1.25	4.25	15.0	20.50
3	1.25	4.0	15.0	20.25
4	1.0	5.0	15.0	21.00
5	1.25	5.5	15.0	21.75
6	1.5	5.5	15.0	22.00
Average	1.29	4.88	15.00	21.17

## Core Location

