

I-77 Southbound Cores - Gore Areas

Core Logs -

Core	Location	Total Depth (in)	Asphalt Depth (in)	OGFC thickness (in)	Distance to Sand Asphalt	Notes
1	A	14	4.5	1.25		No issues - 9.5 inches concrete
2	B	10.5	10.5		5	cored off ogfc
3	C	16	16	1.5	10.75	no visible issues

Core Locations



Core Pictures



Core 1 Location A



Core 1 Picture



Core 2 Location B



Core 2 Picture



Core 3 Location C



Core 3 Picture